MARYLAND HISTORICAL TRUST DETERMINATION OF ELIGIBILITY FORM

NR Eligible: yes _

no ___

Property Name: Baker-Solley Outbuildings	Inventory Number: HA-1297
Address: 3700 Churchville Road City: Aberdeen	Zip Code: 21001
County: Harford County USGS Topographic M	fap: Aberdeen, Maryland, 1985
Owner: Leroy Solley - 3700 Churchville Rd, Aberdeen MD 21001	Is the property being evaluated a district? NO
Tax Parcel Number: 112 Tax Map Number: 51 Tax Account	ID Number: <u>067862</u>
Project: Adams Property A	Agency: Federal Communications Commission
Site visit by MHT Staff: x no yes Name:	Date:
Is the property located within a historic district?yesx_no	
If the property is within a district Distric	t Inventory Number:
NR-listed districtyes Eligible districtyes District	Name:
Preparer's Recommendation: Contributing resourceyesno 1	Non-contributing but eligible in another context
If the property is not within a district (or the property is a district)	
Preparer's Recommendation: Eligibleyes _x_no	
riteria: A B C D Considerations:	A B C D E F G Non
Documentation on the property/district is presented in: Maryland Historic dated September, 1	al Trust Inventory Form for State Historic Sites Survey 1979.
Description of Property and Eligibility Determination: (Use continuation sheet	if necessary and attach map and photo)
The property was most recently observed and its condition appeared to be unchanged since the for State Historic Sites Survey form in the libstrust.	e preparation of the Inventory Form
The property is described in Maryland Historic Sites Survey prepared by Natalie Shive: District Commission, in September 1979. Follow: property description, as modified by site observed.	rs, Harford County Historical ing is a brief summary of that
From the description, the three outbuildings are west). The westernmost barn is two stories with worof. This barn is two bays wide and two bays lor other two buildings are one story and have board a	Vertical board siding and a monitor and appens to the south. The
MARYLAND HISTORICAL TRUST REVIEW	V
Eligibility recommended Eligibility not recommended Criteria: A B C D Considerations:	
Comments:	
	,
Sanoton full 1	nlos
Reviewer, Office of Preservation Services	Date
(3/mt)	1/29/03
Reviewer, NR Program	Date

MARYLAND HISTORICAL TRUST NR-ELIBILITY REVIEW FORM

Continuation Sheet No. 1

HA-1297

south. The easternmost barn also has a monitor roof. The south side has the main entrance and the west end has entrance wood porticos/porch. Fenestration had been 6/6 sash windows with wood and stone lintels. The windows are presently covered with wood boards. It was observed that, with the exception of the covered windows, this property appears virtually unchanged from the description in the attached form.

The property is not associated with any event or personage that would qualify it for eligibility under Criteria A or B, respectively. Although the buildings remain in relatively good condition and are representative examples of ancillary rural buildings of their age, their design and construction do not merit consideration for historic registration under terms of Criterion C. No known archaeological significance is associated with the property, making it ineligible for consideration under Criterion D.

	VESTER STREET	
Pre	pared	by:


William C. Riggs, RA Historic Architect

Date Prepared: 01.28.03

Filed under HA-987

Photo Negative List - Adams Raw Land 09.75132.0272 Ordered by Property Number

	Ordered by Property Roll 1		Roll 2		3	T	T
	Property		Property	Roll Neg	Property	Summary	No Photos- (Bldg. demolished, or not in survey area)
1-33	HA-1294	2-17	HA-0987	3-4	HA-1296	HA-0987	HA-988
1-34	HA-1294	2-18	HA-0987	3-5	HA-1296	HA-0989	HA-1295
1-35	HA-1294	2-19	HA-0987	3-6	HA-1296	HA-0991	HA-1304
1-36	HA-1294	2-2	HA-0989	3-7	HA-1297	HA-0998	HA-1313
1-1	HA-1533	2-3	HA-0989	3-8	HA-1297	HA-0999	
1-2	HA-1533	2-4	HA-0989	3-9	HA-1297	HA-1293	
1-3	HA-1533	2-11	HA-0991	3-10	HA-1297	HA-1294	
1-4	HA-1533	2-12	HA-0991	3-1	HA-1554	HA-1296	
1-5	HA-1533	2-13	HA-0991	3-2	HA-1554	HA-1297	
1-6	HA-1534	2-14	HA-0991	3-3	HA-1554	HA-1533	
1-7	HA-1534	2-15	HA-0991			HA-1534	
1-8	HA-1534	2-16	HA-0991			HA-1535	
1-9	HA-1534	2-33	HA-0998			HA-1536	
1-10	HA-1534	2-34	HA-0998			HA-1553	
	HA-1534		HA-0998			HA-1554	
-	HA-1534		HA-0998			HA-1618	
1-13	HA-1534	2-25	HA-0999			HA-1875	
	HA-1534	2-26	HA-0999				
1-23	HA-1535	2-27	HA-0999				
1-24	HA-1535	2-28	HA-0999				
1-25	HA-1535	2-29	HA-0999				
1-26	HA-1535	2-30	HA-0999				1
_	HA-1535		HA-1293				
	HA-1535		HA-1293				1
_	HA-1535		HA-1293				
	HA-1553		HA-1293				
	HA-1553		HA-1293				
	HA-1553		HA-1536	\neg			
	HA-1553		HA-1536				
	HA-1553		HA-1536	\top			
	HA-1553		HA-1536				
	HA-1553	_	HA-1536	$\neg \neg \neg$		CONTRACTOR SINISTER AS	
	HA-1553		HA-1536	\top		T	T
	HA-1618		HA-1536				
-	HA-1618		HA-1875	1		T	
	HA-1618		HA-1875	1			




SITE VICINITY MAP Aberdeen, MD Quadrangle SCALE: As Shown



Property Condition Assessment HA-1297_ Baker-Solley Outbuildings Aberdeen, MD 21001

HA-1297 Baker-Solley Outbuildings Behind 3700 Churchville Road, Aberdeen Aberdeen quad





HA-1297 BAKER-SOLLEY OUTBUILDINGS 3700 CHURCHVILLE RD, ARERDEEN, HARFORD CO. MD 2100 PHOTO BY: JAMISON STOVER 01.17.03 NEGE MID SHPO SOUTH ELEVATIONS BAKER-SOLLEY OUTBUILDINGS HA-1297 ABERDEEN, MD 21001 01.03